

SURFACE INSPECTION  
COMPLIANCE REPORT

Date of Inspection: 4/3/90

Case Serial No: UT-056-45N

Operator: Richard Hilyard

Project Description: Mining

Legal Description: 21 S., 1 E., 10 SW

District and Resource Area: Richfield, Sevier River

Inspector: Michael Jackson

---

REPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)

---

Doug Thurman and I inspected this notice operation. Activity has ceased, apparently for some time. Disturbance consist of stockpile mounds, one pit, and a road/open cut on the slope. Apparently unusable mining equipment on site included a bulldozer and other equipment. The access road had a sign that stated "Keep Out," which was not authorized under their notice, and it was removed. Also, a fence closed the area, and fence, apparently at times, had been closed to impede entry, again without approval. mcs

Reclamation has not been performed. The site has been left abandoned. The mining equipment should be removed, the pit backfilled and reclaimed, <sup>mounds recontoured and revegetated,</sup> and the road in the draw recontoured and revegetated. mcs

The Jan., 1990, mining claim records indicate that the Grant # 1 and # 2 mining claims have been dropped. Richard Hilyard is also no longer listed in the phone directory. We should send a letter to his previous address, and if undeliverable, then try to locate him.

  
Signature of Inspector

  
Signature of Authorized Officer